

**Client:** Camira Fabrics Ltd  
Meltham Mills  
Meltham  
West Yorkshire  
HD9 4AY

**Entry No:** 68528

**Date received:** 21/01/2015

**Client's Description:** Sample of fabric: Mainline Flax, colour: Archway, Colourcode: HMLF02, Run No: 221010/0510 Call 2978

### TEST REPORT

**Test Required:** Flammability BS 5867-2 : Type B

**Pre-treatment:** Tested before and after one water soaking in accordance with BS EN 1021-1 : 2006, Annex D followed by line drying

**Conditioning:** A minimum of 24 hours at 65 +/- 5% Relative Humidity, 20 +/- 2°C

**Method of Test:** BS EN ISO 15025 : 2002 Procedure A (surface ignition)

**Date of Test:** 02/02/2015

The results may not apply to situations where there is restricted air supply or prolonged exposure to large sources of intense heat as in a conflagration.

#### Flame application time 15 seconds using propane gas

#### As Received

Face of Fabric tested	Fabric length direction			Fabric width direction		
	1↑	2↓	3↑	4→	5←	6→
Specimen number						
Flame reached an edge (✓ or X)	X	X	X	X	X	X
Hole reached an edge (✓ or X)	X	X	X	X	X	X
Flaming debris (✓ or X)	X	X	X	X	X	X

-----End of Page-----

*This is hereby certified to be a correct return of the tests made of the items referred to herein.*



D. Brockbank.  
Materials Testing Manager  
5<sup>th</sup> February 2015



- ❖ Unless instructed otherwise by the client sample remnants will be disposed of after 28 days
- ❖ Test marked (\*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- ❖ Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- ❖ This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



**Client:** Camira Fabrics Ltd  
Meltham Mills  
Meltham  
West Yorkshire  
HD9 4AY

**Entry No:** 68528

**After Water Soak**

Face of Fabric tested	Fabric length direction			Fabric width direction		
	1↑	2↓	3↑	4→	5←	6→
Specimen number						
Flame reached an edge (✓ or X)	X	X	X	X	X	X
Hole reached an edge (✓ or X)	X	X	X	X	X	X
Flaming debris (✓ or X)	X	X	X	X	X	X

**Comments**

On the basis of the tests carried out this sample of fabric meets the Type B requirements of BS 5867-2 : 2008.

-----End of Document-----

*This is hereby certified to be a correct return of the tests made of the items referred to herein.*



D. Brockbank.  
Materials Testing Manager  
5<sup>th</sup> February 2015



- ❖ Unless instructed otherwise by the client sample remnants will be disposed of after 28 days
- ❖ Test marked (\*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- ❖ Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- ❖ This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.

